




ILA-USMX JOINT SAFETY COMMITTEE

OSH Circular 2019-02 (15 February 2019)

Don't Be Caught Under One of These!



While not necessarily every day occurrences, **hoist wires do break; headblocks do accidentally disconnect** (as do hoisted hatch covers); **on-board crane computer systems sometimes malfunction; human beings make mistakes**, etc., etc., etc.

Why roll the dice? Stay out from under any overhead loads; never move a load over anyone's head!

Got an OSH-related question? Write to the JSC at: blueoceana@optonline.net

Working Together For The Benefit Of All

ILA-USMX OSH Circulars are devised to reflect the best possible information and guidance, and are products of diligent research and the most up to date subject matter knowledge. Consequently, while the information contained herein is believed to be accurate, owing to a host of factors ILA-USMX can convey no direct or implied warranty relative to the reliance of parties upon content.